

Inspection Photos

Location Name: PAPPENHEIM-67N64W /26SWSE

Location #: 302874



Colorado Oil & Gas Conservation Commission
40.53836, -104.51545, 4746.7ft, 296°
12/01/2020 13:51:01

Photo #1

Pappenheim 34-26 (05-123-29961) Wellsite

Shut-In | SI

Company / Well name NOT posted

Emergency number NOT posted at well

prior insp.



Colorado Oil & Gas Conservation Commission
40.53784, -104.51584, 4740.7ft, 4°
12/11/2020 15:00:52

Photo #2

Pappenheim 34-26 Wellsite

Plugged & Abandoned | PA

Plugging Operations: Cementing | Final Plugging

Corrective Action for NO signage issues: Clear

Inspection Photos

Location Name: PAPPENHEIM-67N64W /26SWSE

Location #: 302874



Colorado Oil & Gas Conservation Commission
40.53835, -104.51555, 4779.5ft, 195°
12/11/2020 14:57:08

Photo #3

Pappenheim 34-26 (05-123-29961) Wellsite

Plugged & Abandoned | PA

Plugging Operations: Cementing | Final Plugging

Cement to surface

NOT Cut & Capped



Colorado Oil & Gas Conservation Commission
40.54199, -104.50785, 4705.9ft, 318°
12/01/2020 14:34:35

Photo #4

Pappenheim 43-26, 33-26, 34-26, 44-26 Battery site

Inactive | Shut-down.

prior insp.