

Inspection Photos
Operator: Logos Operating
API: 067-08118
Date: 12/9/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with western wheatgrass, largely in a grazed condition.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of the reference area comprised of sagebrush shrubland with grasses such as western wheatgrass in a grazed condition.