

Inspection Photos

API#045-11304

Operator: Terra

Insp#: 692402761

Insp Date: 12/9/20





Photo#1:
Overview of Location to South. Insert PA Marker.

December 9, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra PA Potter HM API#045-11304



Photo#2:
Location fence not removed.



Photo#3:

December 9, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra PA Potter HM API#045-11304



Photo#4:
Location fence not removed.



Photo#5:

December 9, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra PA Potter HM API#045-11304