

Inspection Photos

Loc#335484

Operator: Terra

Insp#: 692402763

Insp Date: 12/11/20





Photo#1:

Overview of Location from entry. Recommended to Post or in some way define newly seeded area to exclude traffic.

December 11, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335484



Photo#2:
Close up of seeded area.



Photo#3:
BMP at Southeast corner of site.

December 11, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335484