

Inspection Photos

Loc#335639

Operator: Terra

Insp#: 692402767

Insp Date: 12/11/20





Photo#1:
Overview of upper level of Location.

December 11, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335639



Photo#2:
Cut slope, upper level. Insert, detail of erosion.



Photo#3:
Cut slope, lower level Insert, detail of erosion

December 11, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335639



Photo#4:
Erosion on cut slopes.



Photo#5:
Erosion on cut slopes.



December 11, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335639