

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2020

Submitted Date:

12/08/2020

Document Number:

698100206

FIELD INSPECTION FORM

Loc ID 335844 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288287	WELL	PR	04/11/2012	GW	045-13180	CASCADE CREEK 697-16-32	EI
290124	WELL	PR	04/01/2020	GW	045-13997	CASCADE CREEK 697-15-01A	EI
290129	WELL	PR	07/11/2012	GW	045-13992	CASCADE CREEK 697-16-31	EI
290130	WELL	PR	09/17/2009	GW	045-13991	CASCADE CREEK 697-16-07	EI
290131	WELL	PR	09/01/2020	GW	045-13990	CASCADE CREEK 697-16-15A	EI
290133	WELL	PR	09/17/2009	GW	045-13988	CASCADE CREEK 697-15-17B	EI
290134	WELL	PR	04/21/2015	GW	045-13987	CASCADE CREEK 697-15-25	EI
290135	WELL	PR	11/24/2008	GW	045-13986	CASCADE CREEK 697-16-06	EI
290136	WELL	PR	10/18/2018	GW	045-13985	CASCADE CREEK 697-15-09A	EI
290138	WELL	PR	01/01/2008	GW	045-13983	CASCADE CREEK 697-09-64	EI

General Comment:

COGCC Environmental inspection. Weather conditions during inspection were sunny with a temperature of 19 degrees Fahrenheit.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Tank placards were peeling off on inspection date. See photos.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	03/08/2021

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Area north of pad is used for storage of steel ASTs and frac tanks. At least one tank in this area was observed with an open access hatch on inspection date. See photos.		
Corrective Action:	Reinstall access hatch panels or other wildlife protection equipment on unused tanks to prevent wildlife access.	Date:	01/08/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	400 BBLS	OTHER		,	
Comment:						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)	2 steel ASTs, 2 heated steel ASTs	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment:	No holes or tears observed in visible portions of liner on inspection date. Accumulation of ice observed inside of secondary containment area. See photos.			
Corrective Action:				
			Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: <u>288287</u>	Type: <u>WELL</u>	API Number: <u>045-13180</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>290124</u>	Type: <u>WELL</u>	API Number: <u>045-13997</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>290129</u>	Type: <u>WELL</u>	API Number: <u>045-13992</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>290130</u>	Type: <u>WELL</u>	API Number: <u>045-13991</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>290131</u>	Type: <u>WELL</u>	API Number: <u>045-13990</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>290133</u>	Type: <u>WELL</u>	API Number: <u>045-13988</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>290134</u>	Type: <u>WELL</u>	API Number: <u>045-13987</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>290135</u>	Type: <u>WELL</u>	API Number: <u>045-13986</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>290136</u>	Type: <u>WELL</u>	API Number: <u>045-13985</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>290138</u>	Type: <u>WELL</u>	API Number: <u>045-13983</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402548806	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305556
698100208	20201204 field photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305553