

## Inspection Photos

Location Name: C15W pipeline release

Spill/Release ID: #478649

Inspection Date: December 14, 2020



**Photo #1 – View of open excavation from southwest. Note proximity of excavation to meter shed and separators as well as presence of multiple flowlines within excavation.**



**Photo #2 – View into open excavation from southwest.**



## Inspection Photos

Location Name: C15W pipeline release

Spill/Release ID: #478649

Inspection Date: December 14, 2020



**Photo #3 – Area off of the well pad to the north was reported terminus of the spill path. Presence of snow on the surface prohibited direct observation of soil and vegetation.**



**Photo #4 – View of fenced excavation area from northeast.**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources