

Inspection Photos

Location 324635

057-06112

Date:12/22020

Photos taken by Kris Neidel



Photo #1 Well upon arrival. Ice looks the same as when discovered on 12/8/20.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos

Location 324635

057-06112

Date:12/22020

Photos taken by Kris Neidel

Photo #2 The temporary repair that was made on 12/8/20 appears to have slowed the release to a drip. Very little ice was observed from the last few days.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos

Location 324635

057-06112

Date:12/22/2020

Photos taken by Kris Neidel



Photo #3 COGCC staff put the ice that was frozen outside of the wellhead shack into pickup truck.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos

Location 324635

057-06112

Date:12/22/2020

Photos taken by Kris Neidel



Photo #4 wellhead after ice removal. Ice was removed by chipping and shoveling.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos

Location 324635

057-06112

Date:12/22/2020

Photos taken by Kris Neidel



Photo #5 The ice was put into Pit #1, Facility #112265



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources