

Final Reclamation Inspection

December 15, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 322652

Inspection Document #: 697502285

Weld County, CO

SESE Section 27 T6N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SWANSON #44-27
Location ID: 322652



Photo 1. Photo taken from the well/battery location, facing Southwest. Photo illustrates the Operator has removed all equipment from location. Location is within a crop field, which appears to be currently fallow.

Inspection Photos
Location Name: SWANSON #44-27
Location ID: 322652



Photo 2. Photo taken from the well/battery location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: SWANSON #44-27
Location ID: 322652



Photo 3. Google earth aerial imagery taken 7/17/2019 illustrates the associated facility that was still servicing a nearby well to the north. Again, all associated equipment has been removed.