

Inspection Photos
Operator: Simcoe
API: 067-09065
Date: 12/15/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is largely snow covered although appears to be sparse and grazed.



Photo 3. View of dense musk thistles along the access road.



Photo 4. View of reference area comprised of irrigated cropland with grassy vegetation largely snow covered at this time.



Photo 5. View of closed gates after leaving location.