

Inspection Photos  
Operator: Simcoe  
API: 067-09690  
Date: 12/15/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is largely snow covered and appears to be progressing with intermediate wheatgrass, crested wheatgrass and sand dropseed.





Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of closed gate after leaving location.