

Final Reclamation Inspection

December 15, 2020

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 333309

Inspection Document #: 697502288

Weld County, CO

NWNW Section 29 T6N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: MATRIX-66N65W 29NWNW

Location ID: 333309



Photo 1. Photo taken from the location, facing South. Photo illustrates Operator has plugged 2 of the 4 wells; therefore, this is a well release on an active location.

Inspection Photos
Location Name: MATRIX-66N65W 29NNW
Location ID: 333309



Photo 2. Photo taken from the location, facing East. See comments under Photo 1.

Inspection Photos

Location Name: MATRIX-66N65W 29NWNW

Location ID: 333309



Photo 3. Photo taken from the location, facing North. See comments under Photo 1.