

**Inspection Photos**  
**Location Name: Vonasek 1**  
**Location ID: 333302**



**Photo 1 Stained soil under load out line East tank**

**Photo 2 Stained soil under loud out line East tank**

Inspection Photos  
Location Name: Vonasek 1  
Location ID: 333302



Photo 1 Stained soil under load out line East tank

Photo 2 Stained soil under loud out line East tank