

## Inspection Photos

Location Name: CAERUS PICEANCE LLC RAMOS-68S96W /1NESW

Location ID: 334104



Photo #2476 from entrance to location.



Photo #2477 from entrance to location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC RAMOS-68S96W /1NESW

Location ID: 334104



**Photo #2478 Multiple holes in tank containment liner.**



**Photo #2480 Multiple holes in tank containment liner.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC RAMOS-68S96W /1NESW

Location ID: 334104



**Photo #2481 Multiple holes in tank containment liner.**