

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/17/2020

Submitted Date:

12/17/2020

Document Number:

693504000

FIELD INSPECTION FORM

Loc ID 302497 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299072	WELL	TA	05/18/2020	OW	123-29239	WELLS RANCH USX AA 13 -02	TA

General Comment:

Inspected Facilities

Facility ID: 299072 Type: WELL API Number: 123-29239 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PREVIOUS INSPECTION

Comment:

Corrective Action: Date:

COGCC Comments

Comment	User	Date
This is a follow up inspection per doc@ 693503901. This well is part of Noble Energy's alternative mechanical integrity assurance program. Previous corrective action has been address by proper paper provided by Noble Energy.	silverr	12/17/2020