

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/17/2020

Submitted Date:

12/17/2020

Document Number:

693504004**FIELD INSPECTION FORM**
 Loc ID 302504 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299091	WELL	TA	05/21/2020	OW	123-29247	WELLS RANCH USX AA 13 -01	TA

**General Comment:**

**Inspected Facilities**Facility ID: 299091 Type: WELL API Number: 123-29247 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: PREVIOUS INSPECTIONComment: Corrective Action: Date: **COGCC Comments**

Comment

This is a follow up inspection per doc@ 693503905. This well is part of Noble Energy's alternative mechanical integrity assurance program. Previous corrective action has been address by proper paper provided by Noble Energy.

User

silverr

Date

12/17/2020