

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/16/2020

Submitted Date:

12/16/2020

Document Number:

701001972**FIELD INSPECTION FORM**

Loc ID 303487 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253182	WELL	PR	06/01/2015	GW	125-07059	BROWN 3-28	PR

General Comment:

Routine Inspection

Location				
Lease Road:				
Type	Access			
comment:	Access off of main gravel road to farm house			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Lease sign mounted to fence			
Corrective Action:				Date:
Type	OTHER			
Comment:	Lease sign for associated wells mounted to meter shed			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Metal panels around wellhead, VGS and meter shed			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Ancillary equipment	# 2			
Comment:	Telemetry equipment and bellows meter for domestic use			
Corrective Action:				Date:
Type: Gas Meter Run	# 3			
Comment:	Shared meter run for BROWN 3-28, 13-28 & 14-28			
Corrective Action:				Date:
Type: Vertical Separator	# 4			
Comment:	3-Vertical gas separators 50% buried by meter shed 1-Vertical gas separator 50% buried by bellows meter for domestic use			
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	253182	Type:	WELL	API Number:	125-07059	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Brown 3-28, 13-28, 14-28) @ 39.85166/-102.19810								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Unable to verify site conditions due to snow coverage](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701001981	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5312870