

Final Reclamation Inspection

December 17, 2020

Operator: CARRIZO OIL & GAS INC - #10338

Location ID: 424422

Inspection Document #: 697502308

Weld County, CO

Lot 4 Section 30 T7N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SLICK ROCK #1-30-11-7-60
Location ID: 424422



Photo 1. Photo taken from the location, facing East. Well location was permitted under a different Location ID (424596). Location was constructed but is currently being operated by Verdad Resources.