

Final Reclamation Inspection

December 17, 2020

Operator: CARRIZO OIL & GAS INC - #10338

Location ID: 425312

Inspection Document #: 697502312

Weld County, CO

SESE Section 21 T7N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Orlando Hill #21-44-7-60
Location ID: 425312



Photo 1. Photo taken from the location, facing North. Well location was not constructed at the proposed location based off field observations.