

# Final Reclamation Inspection

December 17, 2020

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 439738

Inspection Document #: 697502316

Weld County, CO

SWSE Section 31 T7N R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bobcat #O-K-31HNB  
Location ID: 439738



**Photo 1.** Photo taken from the southern location, facing North. Photo illustrates the Operator performed the previous corrective to conduct final reclamation. Location is not reflective of reference areas, as a number of bare patches were observed and annual, weedy vegetation as established.



Inspection Photos  
Location Name: Bobcat #O-K-31HNB  
Location ID: 439738



**Photo 2.** Photo taken from the southwestern location, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: Bobcat #O-K-31HNB  
Location ID: 439738



**Photo 3.** Photo taken from the western location, facing East. See comments under Photo 1. Location is below the red-dashed line; reference area is above the red-dashed line.



Inspection Photos  
Location Name: Bobcat #O-K-31HNB  
Location ID: 439738



**Photo 4.** Photo taken from the western location, facing North. Photo illustrates the vegetative difference between the reference area (outside the red-dashed line) and the location (inside the red-dashed line).



Inspection Photos  
Location Name: Bobcat #O-K-31HNB  
Location ID: 439738



**Photo 5.** Photo taken from the western location, facing West. See comments under Photo 4.



Inspection Photos  
Location Name: Bobcat #O-K-31HNB  
Location ID: 439738



**Photo 6.** Close up photo taken from the location. Photo illustrates the lack of vegetation.



**Photo 7.** Close up photo taken from the western reference area. Photo illustrates the location is not reflective of reference area vegetative cover and composition.