

Final Reclamation and Stormwater Inspection

December 17, 2020

Operator: RED HAWK PETROLEUM LLC - #10503

Location ID: 426701

Inspection Document #: 697502326

Weld County, CO

Lot 3 Section 1 T7N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 1. Photo taken from the entrance of location, facing South. Photo illustrates the location does not appear to meet Rule 1004 vegetative standards. The vegetation-like material in the photo is not actually vegetative growth but straw mulch used during final reclamation activities. There was sparse desirable vegetation observed throughout the location, which is not reflective of reference area vegetation.

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 2. Photo taken from the northern location. Photo illustrates sparse desirable vegetation observed, which is not reflective of reference area vegetation.

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 3. Photo taken from the central location. See comments under Photo 1 and 2.

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 4. Photo taken from the southern location. See comments under Photo 1 and 2.

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 5. Photo taken from the southern location, facing South. See comments under Photo 1 and 2.

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 6. Reference photo taken south of the location. See comments under Photo 1 and 2.

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 7. Photo taken from the entrance of location, facing South. Photo illustrates the reference area to the left of the red-dashed line. See comments under Photo 1 and 2.