

Inspection Photos
Operator: Simcoe
API: 067-08673
Date: 12/17/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Vegetation is largely snow covered at this time.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of dense musk thistles observed along the access road.



Photo 5. View of reference area comprised of grass crop field, largely snow covered at this time.



Photos 6/7. View of closed gates after leaving location.