

# Grizzly Operating GGU 11D Location # 335427

Dec 21, 2020 at 12:04:46 PM  
39.489328,-107.585296 ±4.72m  
COGCC



location

Dec 21, 2020 at 12:05:32 PM  
39.489079,-107.584626 ±4.78m  
COGCC



location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Grizzly Operating  
GGU 11D  
Location # 335427**



**location**



**Pit has been filled**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Grizzly Operating  
GGU 11D  
Location # 335427**



**Debris/unused equipment**



**Debris/unused equipment**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Grizzly Operating  
GGU 11D  
Location # 335427**



**Debris/unused equipment**



**Debris/unused equipment**





**Grizzly Operating  
GGU 11D  
Location # 335427**



**Debris/unused equipment**



**Debris/unused equipment**



**Grizzly Operating  
GGU 11D  
Location # 335427**



**Lack of stabilization**



**Lack of stabilization**

