

Inspection Photos
Location#334786
Operator: Caerus
Inspection #: 692402777
Inspection Date: 12/16/20






Photo#1:
Overview of Location to Northwest.

December 16, 2020



Photo#2:
Tamarisk in Interim area.



Photo#3:
Cut slope area .

December 16, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Couey Location#334786



Photo#4:
Area behind tanks.



Photo#5:
Old signs have been leaned up on separators.
One new sign down.

December 16, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Couey Location#334786