

*Inspection Photos*  
*Loc#334851*  
*Operator: Caerus*  
*Inspection #: 692402778*  
*Inspection Date: 12/16/20*





Photo#1:  
Overview of Location from entry to Northwest. Insert; of area where Marker was down.

December 16, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Benzelloc#334851