

Inspection Photos

Location Name: Lewton Company F Unit 1

Location ID: 320303

Dec 21, 2020 at 1:00:41 PM
39.922982,-104.374294
Strasburg, CO
United States
COGCC



Pic 1 no Placard or capacity on water tank, berms inadequate.

Dec 21, 2020 at 1:01:19 PM
39.923008,-104.374423
Strasburg, CO
United States
COGCC



Pic 2 inadequate berms around tanks, NFPA placard illegible

Inspection Photos

Location Name: Lewton Company F Unit 1

Location ID: 320303



Pic 3 no capacity or Placard on buried vault / berms inadequate



Pic 4 unmarked riser in weeds

Inspection Photos

Location Name: Lewton Company F Unit 1

Location ID: 320303



Pic 5




Pic 6 mechanical issue / stained soil



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Lewton Company F Unit 1
Location ID: 320303



Pic 7



Pic 8 weeds by separator

Inspection Photos

Location Name: Lewton Company F Unit 1
Location ID: 320303

Dec 21, 2020 at 1:05:18 PM
39.923062,-104.373776
Strasburg CO
United States
COGCC



Pic 9 trash on location

Dec 21, 2020 at 1:05:43 PM
39.922997,-104.373683
Strasburg CO
United States
COGCC



Pic 10