

# Inspection Photos

API: 071-06753

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/22/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06753 | Date: 12/22/2020

## Inspection Photos



**Photo 1.** Facing southeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06753 | Date: 12/22/2020

## Inspection Photos



**Photo 2.** Facing toward the well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06753 | Date: 12/22/2020

## Inspection Photos



**Photo 3.** There is an erosion channel at the cut slope which needs to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06753 | Date: 12/22/2020

## Inspection Photos



**Photo 4.** The erosion at south side of the location has been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06753 | Date: 12/22/2020