

# *Inspection Photos*

*Loc#436004*

*Operator: Ursa*

*Inspection Number: 692402787*

*Inspection Date: 12/17/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Knapweed noted at South end of pad on either side of Access road, & on pad perimeter in pasture area.

December 17, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Ursa Valley Farms O Loc#436004



Photo#2:

Knapweed noted at South end of pad on either side of Access road, & on pad perimeter in pasture area.

Photo#3:

December 17, 2020