

Inspection Photos

12/21/2020

Operator: LONE MOUNTAIN PRODUCTION
COMPANY - 51090
Location ID: 312348
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: LONE MOUNTAIN PRODUCTION COMPANY - 51090

Location ID: 312348



Photo 1: Photo taken from the north end of the Location, facing east. Photos 1-4 provide an overview of the Location from east, southeast, southwest to west. Photos also show that the well shares Location with the Premier Bar-X Compressor Station operated by Red Rock Gathering Co.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: LONE MOUNTAIN PRODUCTION COMPANY - 51090

Location ID: 312348



Photo 2: See Comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: LONE MOUNTAIN PRODUCTION COMPANY - 51090

Location ID: 312348



Photo 3: See Comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: LONE MOUNTAIN PRODUCTION COMPANY - 51090

Location ID: 312348



Photo 4: See Comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: LONE MOUNTAIN PRODUCTION COMPANY - 51090

Location ID: 312348



Photo 5: Photo of the fenced reclamation area. Reclamation in process, however vegetative establishment does not appear to be uniform and additional seeding activities will likely be needed to ensure site meets COGCC 1004 standards..



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources