

Interim Reclamation and Stormwater Inspection

December 22, 2020

Operator: BURLINGTON RESOURCES OIL & GAS LP- #26580

Location ID: 428353

Inspection Document #: 697502330

Adams County, CO

NENE Section 19 T3S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: VENTURERS /41-4H
Location ID: 428353



Photo 1. Photo taken from the southern entrance of location, facing North. Photo illustrates the Operator sign. Note- Form 10 is in process.

Inspection Photos
Location Name: VENTURERS /41-4H
Location ID: 428353



Photo 2. Photo taken from the northeastern stormwater BMP/landscaped area, facing Southeast. Photo illustrates unmanaged Kochia and Russian thistle weeds.

Inspection Photos
Location Name: VENTURERS /41-4H
Location ID: 428353



Photo 3. Photo taken from the northeastern location, facing Southwest. Photo illustrates a sediment trap which appears to be in proper functioning condition at the time of this inspection.

Inspection Photos
Location Name: VENTURERS /41-4H
Location ID: 428353



Photo 4. Photo taken from the southern location, facing East. Photo illustrates the landscaping area in being properly managed.

Inspection Photos
Location Name: VENTURERS /41-4H
Location ID: 428353



Photo 5. Photo taken from the northwestern location, facing North. See comments under Photo 4.

Inspection Photos
Location Name: VENTURERS /41-4H
Location ID: 428353



Photo 6. Photo taken from the southern location, facing East. Photo illustrates Operator has performed interim reclamation activities.

Inspection Photos
Location Name: VENTURERS /41-4H
Location ID: 428353



Photo 7. Photo taken from the southern location, facing North. See comments under Photo 6.

Inspection Photos
Location Name: VENTURERS /41-4H
Location ID: 428353



Photo 8. Photo taken from the northwestern interim reclamation area. Photo illustrates the germination of winter wheat.