

Inspection Photos
Location Name: Horsetail 02D-0204
Location ID: 437025



Photo 1 – Location Signs at Entrance

Photo 2 – Tank Battery

Inspection Photos
Location Name: Horsetail 02D-0204
Location ID: 437025



Photo 3 – Heater Treater



Photo 4 – Wellhead, Stained Soil

Inspection Photos
Location Name: Horsetail 02D-0204
Location ID: 437025



Colorado Oil and Gas Conservation Commission
40.87473, -103.72445, 4759.9ft, 223°
12/22/2020 12:23:27



Colorado Oil and Gas Conservation Commission
40.87485, -103.72512, 4709.0ft, 219°
12/22/2020 12:23:52

Photo 5 – Stained Soil at Exhaust

Photo 6 – Stained Soil at Pumping Unit

Inspection Photos
Location Name: Horsetail 02D-0204
Location ID: 437025



Photo 7 – Stained Soil at Supply Pot



Photo 8 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Horsetail 02D-0204
Location ID: 437025




Photo 7 – Stained Soil at Gas Engine



Photo 8 – Stained Soil at Gas Engine