

Inspection Photos
Location Name: Horsetail 07E PAD
Location ID: 431527



Photo 1 – Location Signs at Entrance

Photo 2 – Wellhead

Inspection Photos
Location Name: Horsetail 07E PAD
Location ID: 431527



Photo 3 – 07E-1836 Wellhead missing Sign




Photo 4 – 07E-1802 Wellhead missing Sign

Inspection Photos
Location Name: Horsetail 07E PAD
Location ID: 431527



Photo 5 – Gas Meter Houses