

Inspection Photos
Location Name: Horsetail 29G PAD
Location ID: 435861



Photo 1 – Location Signs at Entrance



Photo 2 – Tank Battery



Inspection Photos
Location Name: Horsetail 29G PAD
Location ID: 435861



Photo 3 – Heater Treaters



Photo 4 – 29G-2012B Pumping Unit

Inspection Photos
Location Name: Horsetail 29G PAD
Location ID: 435861




Photo 3 – Stained Soil at 29G-2043 Wellhead



Photo 4 – Wellhead Sign

