

Final Reclamation Inspection

December 22, 2020

Operator: AXIS EXPLORATION LLC - #10646

Location ID: 320193

Inspection Document #: 697502332

Weld County, CO

SWSW Section 5 T3S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: QUALLS #5-13
Location ID: 320193



Photo 1. Photo taken from the southern tank battery location, facing East. Photo illustrates Operator has failed to removed all gravel and perform final reclamation activities.

Inspection Photos
Location Name: QUALLS #5-13
Location ID: 320193



Photo 2. Photo taken from the southern tank battery location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: QUALLS #5-13
Location ID: 320193



Photo 3. Photo taken from the well location access road, facing East. Operator has failed to properly contour and perform final reclamation activities.

Inspection Photos
Location Name: QUALLS #5-13
Location ID: 320193



Photo 4. Photo taken from the well location, facing East. Operator has failed to properly contour and perform final reclamation activities.

Inspection Photos
Location Name: QUALLS #5-13
Location ID: 320193



Photo 5. Photo taken from the northern location, facing East. Operator has failed to remove all equipment, regardless of ownership.