

Inspection Photos

Location Name: LARAMIE ENERGY LLC Horseshoe Canyon /2-17 Pad

Location ID: 312621



Photo #2506 from entrance to location.



Photo #2507 Braden head valves are not accessible.