

Inspection Photos

Location Name: LARAMIE ENERGY LLC Horseshoe Canyon /1-20 Pad

Location ID: 312621



Photo #2508 from entrance to location.



Photo #2509 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Horseshoe Canyon /1-20 Pad

Location ID: 312621



Photo #2510 Braden head valves are not accessible.