

Simms E #1 & #3
Photographic Log
Simcoe LLC



Photo 1: Simms E #1 & #3 well sign, 11/6/2020.



Photo 2: Point of release, 11/6/2020.



Photo 3: Well pad and wet area, 11/6/2020.



Photo 4: SS01 collected near the point of release, 11/6/2020.




Photo 5: SS02 collected from the wet area, 11/6/2020.




Photo 6: SS03 collected from the wet area, 11/6/2020.



Photo 7: SS04 collected as a background sample, 11/6/2020.



Photo 8: WS01 collected from the wet area, 11/6/2020.



Photo 9: SS05 collected as a vertical characterization sample, 11/23/2020.



Photo 10: SS06 collected as a vertical characterization sample, 11/23/2020.