

Bradenhead Pressure Action Threshold 508 psig

This threshold is calculated per Rule 308A.b.(2)G. If this well is located in a bradenhead test area (see Rule 207.b) per an Order of the Commission, it may be subject to a different threshold.

Does the casing centralization comply with Rule 317.g? Yes

If "NO", provide details below.

STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: _____

| Method used | String | Cementing tool setting/perf depth | Cement volume | Cement top | Cement bottom |
|-------------|--------|-----------------------------------|---------------|------------|---------------|
| | | | | | |

Details of work:

FORMATION LOG INTERVALS AND TEST ZONES

| FORMATION NAME | Measured Depth | | Check if applies | | COMMENTS (All DST and Core Analysis must be submitted to COGCC) |
|----------------|----------------|--------|------------------|-------|---|
| | Top | Bottom | DST | Cored | |
| | | | | | |

Operator Comments:

Only the surface portion of this well was drilled and surface casing set. Drilling activity was suspended on 9/7/2020 and is anticipated to commence on 3/2/2021.
Top of Productive Zone and Bottom hole footages are based on approved APD footages due to drilling activity being suspended. Footages will be corrected on the final Form 5 submission.
Well was drilled prior to adoption of WBI Rules and vendor did not create pressure chart to accompany cement verification report.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Ally Ota

Title: Regulatory Analyst Date: 12/3/2020 Email: alexandria.ota@pdce.com

Attachment Check List

| Att Doc Num | Document Name | attached ? | |
|-----------------------------|-----------------------|---|--|
| <u>Attachment Checklist</u> | | | |
| 402543312 | CMT Summary * | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| | Core Analysis | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| 402545333 | Directional Survey ** | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| | DST Analysis | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| | Logs | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| | Other | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| <u>Other Attachments</u> | | | |
| 402543285 | FORM 5 SUBMITTED | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| 402545334 | DIRECTIONAL DATA | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|---|---------------------|
| Engineering Tech | Corrected Field Name Corrected surface string cmt btm per attached directional survey Passed engineering review | 12/28/2020 |

Total: 1 comment(s)

