

**Inspection Photos**  
**Location Name: State 36-3-63 #1H**  
**Location ID: 423568**



**Photo #1 Well**



**Photo #2 Unused Equipment "Rod"**



**Inspection Photos**  
**Location Name: State 36-3-63 #1H**  
**Location ID: 423568**



**Photo #3 Unused Equipment**




**Photo #4 Tank Battery**



**Inspection Photos**  
**Location Name: State 36-3-63 #1H**  
**Location ID: 423568**



**Photo #5 Production Equipment**



**Photo #6 Flare**



**Inspection Photos**  
**Location Name: State 36-3-63 #1H**  
**Location ID: 423568**



**Photo #7 Surface Casing has no Bradenhead provisions (Not Plumbed to Surface)**



**Photo #8 Surface Casing has no Bradenhead provisions (Not Plumbed to Surface)**