

Inspection Photos
Location Name: Horsetail 30E PAD
Location ID: 445049




Photo 1 – South Wellheads, 30E-3103 missing Sign




Photo 2 – North Wellhead, 30E-1935 missing Sign



Inspection Photos
Location Name: Horsetail 30E PAD
Location ID: 445049



Photo 3 – 30E-1934 missing Wellhead Sign