

Inspection Photos
Location Name: Horsetail 18-0733H
Location ID: 425520



Photo 1 – Location Signs at Entrance

Photo 2 – Pumping Unit



Inspection Photos
Location Name: Horsetail 18-0733H
Location ID: 425520



Photo 3 – Heater Treater



Photo 4 – Tank Battery



Inspection Photos
Location Name: Horsetail 18-0733H
Location ID: 425520



Photo 5 – ECD and Flare



Photo 6 – Stained Soil at Condensate Tank