

Inspection Photos
Operator: Simcoe
API: 067-08885
Date: 12/22/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern fill slope from the northeastern corner facing westward. Location largely snow covered, although perennial vegetation such as intermediate wheatgrass, smooth brome, and rubber rabbitbrush is observable.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with gambel oak, antelope bitterbrush, Indian ricegrass, and mountain mahogany.



Photo 5. View of closed gate after leaving location