

# Inspection Photos

11/24/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334411

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334411



**Photo 1:** Photo taken northeast of the Location. Photo for documentation purposes. Photo shows gate along access road to Location is broken. Reclamation specialist accessed location on foot and did not travel through gate with a vehicle.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334411



**Photo 2:** See comments under photo 1.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334411



**Photo 3:** Photo taken from the northeast corner of the Location, facing south. Photo provides an overview of the Location and reclamation area.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334411



**Photo 4:** Photo taken from the northeast corner of the Location, facing west. Photo provides an overview of the Location and reclamation area. .



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334411



**Photo 5:** Photo taken from the northwest end of the Location. Photo shows culvert and drainage. Culvert has not been installed in accordance with good engineering practices and is missing proper inlet/outlet protection.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334411



**Photo 6:** Photo taken from the central area of the Location, facing north. Photos 6-9 provide an overview of the Location from north, east, south to west.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334411



**Photo 7:** See comments under photo 6.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334411



**Photo 8:** See comments under photo 6.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334411



**Photo 9:** See comments under photo 6.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334411



**Photo 10:** Photo taken from the west end of the Location. Photo shows vegetation establishment on the west and northwestern areas of the Location is predominantly weedy annual grass species such as cheat grass. Cheat grass may be hindering desirable vegetative establishment and additional seeding and weed management may be required to facilitate reclamation