

Inspection Photos

11/24/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 312673

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312673



Photo 1: Photo taken northwest of the Location, facing southeast. Photo provides an overview of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312673



Photo 2: Photo taken from the east end of the Location, facing west. Photo shows graveled “turn-around” area left per the variance.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312673



Photo 3: Photo taken from the east end of the Location, facing northwest. Photo shows graveled "turn-around" area left per the variance.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312673



Photo 4: Photo taken from the east end of the Location, facing west. Photo provides an overview of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312673



Photo 5: Photo taken from the east end of the Location, facing northwest. Photo provides an overview of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312673



Photo 6: Photo taken from the northwest end of the Location, facing west. Photo shows areas where additional reclamation has been performed.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312673



Photo 7: Photo taken from the northwest end of the Location, facing south. Photo shows areas where additional reclamation has been performed.