

Inspection Photos

11/24/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 312461

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312461



Photo 1: Photo taken from the south end of the Location, facing northwest. Photo shows areas on the west end of the Location that remain bare and will likely require additional reclamation work for Location to meet 1004 Standards; At least 2 growing seasons have passed since well was PA, plant germination should be evident on these areas. Evidence of equipment/vehicle travel also observed on the areas; Additional compaction alleviation may also be necessary.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312461



Photo 2: Photo taken from the south end of the Location, facing north. See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312461



Photo 3: Photo taken from the north end of the Location, facing southeast. Vegetation establishment in these areas appears to be progressing towards COGCC reclamation requirements.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312461



Photo 4: Photo taken from the north end of the Location, facing south. Photo shows areas on the west end of the Location that remain bare and will likely require additional reclamation work for Location to meet 1004 Standards; At least 2 growing seasons have passed since well was PA, plant germination should be evident on these areas. Evidence of equipment/vehicle travel also observed on the areas; Additional compaction alleviation may also be necessary.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312461



Photo 5: See comments under photo 4.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312461



Photo 6: Photo shows example of Noxious weed rosettes observed on the Location.