

Inspection Photos
Operator: Simcoe
API: 067-08932
Date: 12/23/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Project area is largely snow covered. Perennial vegetation such as smooth brome, crested wheatgrass, and western wheatgrass observable.



Photo 3. View of Russian knapweeds observed along the access road, near the well pad entrance. Approximately 50 individuals observed.



Photo 4. View of reference area (in background), comprised of open grass field with smooth brome.



Photo 5. View of closed gate after leaving location