

Inspection Photos  
Operator: Simcoe  
API: 067-07328  
Date: 12/23/2020



Photo 1. View of the project area from the well pad entrance facing center.





Photo 2. View of the southern project area from the southeastern corner facing westward. Perennial vegetation such as smooth brome, crested wheatgrass, and western wheatgrass observable.





Photo 3. View of the western project area from the southwestern corner facing eastward.





Photo 4. View of reference area (in background), comprised of open grass field with smooth brome, sagebrush, and gamel oak.



Photo 5. View of closed gate after leaving location