

Inspection Photos
Operator: Simcoe
API: 067-06767
Date: 12/23/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Perennial vegetation such as smooth brome and sand dropseed observable.



Photo 3. View of vegetation within the northern project area, appears to be progressing.



Photo 4. View of closed gate after leaving location