

## Inspection Photos

Location Name: 31 OPERATING ANT HILL UNIT-62N96W /19SENE

Location ID: 316311



Photo #2525 from entrance to location.



Photo #2527 Figure 200 hammer union rusted and cracked.