

Inspection Photos  
Operator: Simcoe  
API: 067-08733  
Date: 12/23/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Perennial vegetation such as smooth brome, crested wheatgrass, and sand dropseed observable.





Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of reference area comprised of open grass field with smooth brome and crested wheatgrass.





Photo 5. View of closed gate after leaving location